




Mustang Cat Marine Svc, LLC. 7001 Easthaven Blvd Houston, TX 77017 (713) 452-5250 mustangcat.com

		<u>e Report</u>	Page1of1
Customer Name: Harris	•		02382
Contact Person: Ray Lor			AKE CHARLES
Contact Ph: (757) 342 39	960	Engine Hours:	
Work Location:	MANCHESTER TERMINAL		
Service Call Details	7 ENGINES WITH AN INSPECTION ON 3 OF THE	M	
Model: C280		Problem Type: INS	PECTIONS
Equipment: Generator		Call Type:	
Equip/Vessel:		Serial No.: O Port	NIK BUUT SU
9	Subject:		
CYLINDERS 15,13,11 A CYLINDERS. ALL THE L GOES FOR THE PISTO ROLLED OVER JUST FOR	E COVERS AND LOOKED AT ALL THE ROCKE AND 7. WE PULLED THE ROCKER ARMS AN INNERS STILL HAD THEIR CROSS HATCHING NS. OVERALL HEALTH OF THIS ENGINE IS GIVE. Sectures showing the cylinder liners, valves, cylinder liners is in good condition, all valves.	D THEN PULLED THE INJECTORS WITH NO SIGNS OF WASH OUT GREAT. ENGINE DOES NOT SEEM and piston heads, all showing to	OUT THEN SCOPED THE OR ANY OTHER DAMAGE. SAME TO HAVE ANY LEAKS AND IT o be in great condition. The
debris sitting on top of	of the pistons.		
		6/26/2023	Drake Charles
Authorized Customer Repres	sentative (Print)	Date	Technician















Mustang Cat Marine Svc, LLC. 7001 Easthaven Blvd Houston, TX 77017 (713) 452-5250


				mustangcat.co
Service Report		Page	e <u>1</u>	of 1
· ·	arine Job #:	ME02382		
Contact Person: Ray Lorenzo Teo	chnician:	DRAKE CHA	ARLES	
Contact Ph: (757) 342 3960 En	gine Hours:			
Work Location: MANCHESTER TERMINAL				
Service Call Details 7 ENGINES WITH AN INSPECTION ON 3 OF THEM				
Model: C280 Pro	oblem Type:	INSPECTIO	NS	
Equipment: Generator Cal	ıll Type:			
Equip/Vessel: Ser	rial No.:	o Port o Starboard	NKB00177	
Subject:				
Service Details REMOVED THE VALVE COVERS AND LOOKED AT ALL THE VALVE TRAIN. NEXT WE THE ROCKER ARMS AND THEN PULLED THE INJECTORS OUT THEN SCOPED THE CYCROSS HATCHING WITH NO SIGNS OF WASH OUT OR ANY OTHER DAMAGE. SAM OF THIS ENGINE IS GREAT. ENGINE DOES NOT SEEM TO HAVE ANY LEAKS AND IT HAVE A LITTLE BIT OF SURFACE RUST ON THE BOTTOM OF THE HEAD AND ALSO TO BE ALARMED ABOUT. THATS NORMAL FOR HOW LONG THESE ENGINE'S HAVING BEIOW you can find pictures of the cylinder liners, valves, and piston heads, all sh crosshatching in the cylinder liners is in good condition, all valves look to be seat debris sitting on top of the pistons. There is some slight surface rust that is to be running. This will clear up without impacting the function or lifespan of the engire and the engine of the cylinder liners is a some slight surface. Authorized Customer Representative (Print)	YLINDERS. IE GOES FO ROLLED O ON THE LI TE BEEN SIT Howing to led proper Expected The expected T	ALL THE LINDER THE PISTONER JUST FILE NERS THEM ITING. The in good color of the pilone in good color of the pilone in good color of the pilone in good the good the pilone in good the good the good the good the good the	NERS STILL HONS. OVERANE. CYLINDE SELVES, BU Condition. The	AD THEIR LL HEALTH RS 2,4 AND F NOTHING e kings or not been







Cylinder #2 CYlinder # 2 Cylinder #12 Chinder #12 Chinder # 2







Mustang Cat Marine Svc, LLC. 7001 Easthaven Blvd Houston, TX 77017 (713) 452-5250


mustangcat.com Service Report Page ME02382 Customer Name: Harris Companies Marine Job #: Contact Person: Ray Lorenzo **DRAKE CHARLES** Technician: Contact Ph: (757) 342 3960 **Engine Hours:** Work Location: MANCHESTER TERMINAL 7 ENGINES WITH AN INSPECTION ON 3 OF THEM Service Call Details Model: C280 Problem Type: INSPECTIONS Equipment: Generator Call Type: O Port Equip/Vessel: Serial No.: NKB00174 Subject: **Service Details** REMOVED THE VALVE COVERS AND LOOKED AT ALL THE VALVE TRAIN. NEXT WE SCOPED CYLINDERS 15,13,11 AND 9. WE PULLED THE ROCKER ARMS AND THEN PULLED THE INJECTORS OUT THEN SCOPED THE CYLINDERS. ALL THE LINERS STILL HAD THEIR CROSS HATCHING WITH NO SIGNS OF WASH OUT OR ANY OTHER DAMAGE. SAME GOES FOR THE PISTONS. OVERALL HEALTH OF THIS ENGINE IS GREAT. THESE CYLINDERS WERE THE BEST OUT OF THE BUNCH. NOT ONE SINGLE PROBLEM FROM THIS UNIT. AFTER PUTTING EVERYTHING BACK TOGETHER WE ROLLED THE ENGINE OVER WITHOUT ANY PROBLEM. The pictures below were taken with a bore scope and show the condition of the top of the pistons, cylinder liners, and valves. All look to be in great condition with minimal surface rust. This engine was well preserved and looks to have a lot of life left in it. 6/26/2023 **Drake Charles** Date Technician Authorized Customer Representative (Print)


Ver 13120


Authorized Customer Representative (Signature)


Cylinder #19 #15 Cylinder 15 # 15 Cylinder 15 Minder 15

Cylinder 15 Cylinder 15 #13















Mustang Cat Marine Svc, LLC. 7001 Easthaven Blvd Houston, TX 77017

Houston, TX 77017 (713) 452-5250 mustangcat.com

	<u>Service</u>	Report	Pa	nge <u>1</u> of <u>1</u>
Customer Name: Harris Comp		Marine Job #:	ME02382	2
Contact Person: Ray Lorenzo		Technician:	DRAKE C	HARLES
Contact Ph: (757) 342-3960		Engine Hours:		
Work Location:	MANCHESTER TERMINAL			
Service Call Details	7 ENGINES WITH AN INSPECTION ON 3 OF THEM			
Model: C280		Problem Type:	INSPECTI	ONS
Equipment: Generator		Call Type:		
Equip/Vessel:		Serial No.:	O Port o Starboard	NKB00176
Subje				
ANY SIGNS OF LEAKS OR I	DAMAGE. NO SIGNS OF LEAKS WHILE DO	ING MY INSPECTIONS.EV	ERYTHING	S LOOKED TO BE IN
		6/26/2023		Drake Charles
Authorized Customer Representat	ive (Print)	Date		Technician










Mustang Cat Marine Svc, LLC. 7001 Easthaven Blvd Houston, TX 77017 (713) 452-5250

mustangcat.com

	Service Re	port Page1	of1	
Customer Name: Harris Companies		Marine Job #: ME02382		
Contact Person: Ray Lorenzo		Technician: DRAKE CHARLES		
Contact Ph: (757) 342 3960		Engine Hours:		
Work Location:	MANCHESTER TERMINAL			
Service Call Details	7 ENGINES WITH AN INSPECTION ON 3 OF THEM			
Model: C280		Problem Type: INSPECTIONS		
Equipment: Generator		Call Type:		
Equip/Vessel:		Serial No.: OPORT OF STATE OF	.75	
Sub	oject:			
ANY SIGNS OF LEAKS OF GOOD CONDITION.	R DAMAGE. NO SIGNS OF LEAKS WHILE DOING	MY INSPECTIONS. EVERYTHING LOOKED 1	O BE IN	
		_ 6/26/2023 Drake Ch		











Mustang Cat Marine Svc, LLC. 7001 Easthaven Blvd Houston, TX 77017 (713) 452-5250

mustangcat.com

Service Report Page ME02382 Customer Name: Harris Companies Marine Job #: Contact Person: Ray Lorenzo Technician: **DRAKE CHARLES** Contact Ph: (757) 342-3960 **Engine Hours:** Work Location: MANCHESTER TERMINAL Service Call Details 7 ENGINES WITH AN INSPECTION ON 3 OF THEM Model: C280 Problem Type: INSPECTIONS Equipment: Generator Call Type: O Port Equip/Vessel: Serial No.: NKB00178

Service Details

ROLLED THE ENGINE OVER AFTER CUTTING THE WRAPS OFF THE ENGINE. I ALSO DID A WALK AROUND AND CHECKED FOR ANY SIGNS OF LEAKS OR DAMAGE. NO SIGNS OF LEAKS WHILE DOING MY INSPECTIONS. EVERYTHING LOOKED TO BE IN GREAT CONDITION.

	_ 6/26/2023	Drake Charles	
Authorized Customer Representative (Print)	Date	Technician	
Authorized Customer Department (Circustoms)			
Authorized Customer Representative (Signature)			

Ver 13120









Mustang Cat Marine Svc, LLC. 7001 Easthaven Blvd Houston, TX 77017

(713) 452-5250 mustangcat.com

	<u>Service</u>	Report	Page	of
Customer Name: Harris (Marine Job #:		
Contact Person: Ray Lore		Technician:	DRAKE CHAF	RLES
Contact Ph: (757) 342-39		Engine Hours:		
Work Location:	MANCHESTER TERMINAL			
Service Call Details	7 ENGINES WITH AN INSPECTION ON 3 OF THEM			
Model: C280		Problem Type:	INSPECTION	S
Equipment: Generator		Call Type:		
Equip/Vessel:		Serial No.:	o Port o Starboard	NKB00179
Service Details ROLLED THE ENGINE	OVER AFTER CUTTING THE WRAPS OFF THE OR DAMAGE. NO SIGNS OF THE LEAKS WHILION.			
Authorized Customer Repres	ontative (Print)	<u>6/26/2023</u> Date		<u>Drake Charles</u> Technician
Authorized Custoffier Repres	entative (Fillit)	Date		recinician